

TIPS FOR COATERS

PRISMATIC POWDERS

Learn and understand cure times.

Problem. How do I get the best look and results from my powder coating?

Solution. The most important step is to learn and understand cure times. The most common mistakes made have to do with curing. Have the proper equipment in your powder coating shop and learn how to gauge part temperature accurately so you know when to start your curing timer. Cure times do not start until parts have reached the full curing temperature, also known as



Part Metal Temperature. The most essential equipment every powder coating shop should have include the Infra-Red Temperature Gun, Mil Thickness Gauge and Powder Coating Fluidizer.

**Prismatic Powders
White City, OR 97503
1-866/774-7628
www.PrismaticPowders.com**